

**Rothenberg & Co.**  
West 14th St.

A close-up photograph of a concrete wall. A prominent horizontal crack runs across the middle of the frame. Above this crack, there is a vertical crack that extends upwards. The concrete surface is textured and shows signs of weathering.